

The schematic diagram illustrates a mechanical assembly consisting of two main parts, labeled 1a and 1b, which are connected to a common horizontal shaft or frame. Part 1a is shown on the left, and part 1b is shown on the right. Each part has a vertical rectangular component (4a and 4b) mounted on top. A horizontal bar (6a and 6b) is positioned below each vertical component. The entire assembly is supported by a series of rollers or guides (2, 2a, 2b) mounted on a base (7, 8). The components are interconnected via various linkages and pivots (9, 9', 10, 10').

Figure 1 is a schematic diagram of a mechanical assembly. It shows two main units, 4a and 4b, mounted on a common base. Unit 4a is connected to a base 1 via a linkage 2, which includes a pivot 1a and a spring 5a. Unit 4b is connected to a base 1b via a linkage 2, which includes a pivot 1b and a spring 5b. The assembly is supported by a base 9 and 9'.

FIG. 3

2/7




FIG. 4




FIG. 5A




FIG. 5B

3/7




FIG. 6A




FIG. 6B

4/7




FIG. 7A




FIG. 7B

5/7




FIG. 8A




FIG. 8B

6/7




FIG. 9A




FIG. 9B

7/7




FIG. 10